



5/019/035

"FILE COPY"

Moab District
Grand Resource Area
885 South Sand Flats Road
Moab, Utah 84532

3890
UTU-72488 ✓
(UT-068)

CERTIFIED MAIL--Return Receipt Requested
Certification No. Z 007 272 238

JUL 27 1994

Mr. Don Dallape
Absolute Mining & Minerals, Inc., (AMMI)
1350 East 145 South
Lehi, Utah 84043

Re: Need for Additional Information Regarding Tailings Reclamation Plan of Operations,
Covering Parts of T. 23 S., R. 24 E., SLM, Section 11: Lot 5, Lot 7, Grand County,
Utah

Dear Mr. Dallape:

Thank you for submitting your new Plan of Operations, dated July 14, 1994, for tailings reclamation of the above referenced areas. We received it at our office on July 18, and have assigned this Plan the serial number UTU-72488. Please refer to this case file number in all future correspondence with us regarding it.

We have made a preliminary review of information contained in this plan and have found deficiencies in the required information. As a result, we cannot proceed with analysis of your reclamation plan as presented. The cleanup of junk vehicles, trash, and other material not needed for mining operations is, however, to proceed without delay.

Please provide the following additional information, required by 43 CFR 3809.1-5 (you have already received a copy of 43 CFR 3809 Surface Management Regulations from this office):

43 CFR 3809.1-5(c)(1): Correct claimant information.

43 CFR 3809.1-5(c)(2): Topographic map (preferably 7-1/2 minute) coverage of area to be disturbed/redisturbed, showing, as much as possible, location(s) and area(s) of proposed tailings reclamation activity. On the same map, show location, and indicate dimensions of access routes (existing and/or proposed). Give details of source(s) and quantities of materials needed for access route purposes. Give a definite estimate of total acreage to be disturbed/redisturbed; this will be a very important factor in reclamation bond calculation for this proposed mining (not exploration) plan.

43 CFR 3809.1-5(c)(4): Be as specific as possible; in addition, discuss the following:

- (a) Surface facilities to be utilized; surface facilities to be removed when operations are completed.
- (b) An estimate of the number of cubic yards of tailings to be processed, as well as an estimate of the amount of water required for operations; number of people involved in operations, and how they are used; amount and type of equipment, vehicles involved in this project.

43 CFR 3809.1-5(c)(5): Include in this section a discussion the following: dust suppression measures to be taken; measures to be taken to help minimize erosion; sanitary measures/facilities. Provide as much detail as possible regarding the reclamation process AMMI intends to employ.

43 CFR 3809.1-5(c)(6): Provide, in as much detail as possible, this information.

Should you have questions, please contact Sal Venticinque of my staff at (801)259-8193.

Sincerely,

/s/ Joe Cresto, Acting

Area Manager

SVenticinque:caf:7/27/94 C:\SW-BIN AMMI

the reverse side?

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, and 4a & b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

1. ☐ Addressee's Address
2. ☐ Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:
Mr. Don Dallape
Absolute Mining & Minerals
1350 East 145 South
Lehi, Utah 84043

4a. Article Number
Z Z 007 272 238

4b. Service Type
☐ Registered ☐ Insured
☒ Certified ☐ COD
☐ Express Mail ☐ Return Receipt for Merchandise

7. Date of Delivery
2/28

8. Addressee's Address (Only if requested and fee is paid)

Sal Venticinque

Signature (Addressee)

Signature (Agent)

311, December 1991

☆U.S. GPO: 1993-352-714

DOMESTIC RETURN RECEIPT

Thank you for using Return Receipt Service.